



STEP 1



STEP 2




Hammer mount (1)





M4x65 Brass spacer (1)



M4 x 12 Phillips screw (1)




STEP 3



STEP 4

	M4x35 Phillips combination screw (1)
	M4 Nut (1)
	M4 Spacer (1)




STEP 5



Barrel 4.0 (1)



M3 x 8 Phillips screw (4)



STEP 6



dispenser kit II (1)




Spring (1)





M3x4+6 M-F Brass spacer (1)



M3×16 Phillips screw (1)



STEP 7



STEP 8




180° Servo (1)



M4 x 16 Phillips screw (4)



M4 Nut (4)



STEP 9



Servo Gear IV (1)




Servo horn (1)



M3 x 12 Phillips screw (1)



M3 x 6 Phillips screw (4)




STEP 10



New Base B (1)



M3 × 10 Phillips screw (4)



STEP 11



360° Servo (1)



IR to servo mount (1)



IR sensors (1)



M3×10 Phillips screw (1)




M3 Nut (1)



M4×16 Phillips screw (2)



M4 Nut (2)



STEP 12



Hammer Loader (1)



Servo horn (1)



M3x7x2 Plastic spacer (2)



M3x14 Phillips combination screw(1)



M3x12 Phillips combination screw(1)



M2 Washer (1)




M2 Split lock washer (1)



M2 Nut (1)



M2x10 Phillips countersunk screw (1)




STEP 13



M4 × 10 Phillips screw (1)



M4 × 16 Phillips screw (1)



STEP 14

